

Basic and angle cuts

Use this diagram to position your crown moulding according to the cut you wish to obtain.

N.B. Always invert the crown moulding inside the mitre box, i.e. the ceiling side of the moulding must be placed on the cutting table of the mitre box (the cove of the moulding generally goes against the wall portion).

